

West Fork Dairy Creek Restoration Project
Photo-point Site 5 --- West Fork Dairy Creek stream reach located on Stub Stewart State
Park property (directly downstream of Site 6), looking downstream



(Pre-Project): Most upstream end of West Fork Dairy Creek culvert.



(Post-Project) Looking downstream at stream channel
Following removal of stream crossing (road fills and culverts).



Year 1 (2009) Looking downstream



Year 3 (2011) Looking downstream